Search Notes

Application/Control No.	_
-------------------------	---

Applicant(s)/Patent under Reexamination

10/771,083

Examiner

HOFMEISTER ET AL.
Art Unit

Toan M. Le

2863

	SEARCHED				
Class	Subclass	Date	Examiner		
702	120	5/24/2005	TL		
372	38.1	5/12/2005	TL		
372	50	5/12/2005	TL		
257	688	5/20/2005	TL		
385	92	5/20/2005	TL		
385	93	5/20/2005	TL		
372	38.02	5/23/2005	TL		
Above	Updated	12/22/2005	TL		
Above	Updated	7/21/2006	TL		
398	135	7/21/2006	TL		

INTERFERENCE SEARCHED					
Class	Subclass	Date	Examiner		
	<u> </u>				

SEARCH NOT (INCLUDING SEARCH))
	DATE	EXMR
Electrostatic Discharge Damage, Photodiode, Laser	5/12/2005	TL
Laser Diode, Switch, Transceiver, Pins	5/12/2005	TL
Transceiver Module, Laser Diode	5/12/2005	TL
VCSEL, Laser Drive, Laser Diode, Transceiver	5/23/2005	TL
702/120; 372/38.1,38.02; 257/688; 398/135 (Laser Diode)	7/21/2006	TL
East-See Search History Printout	7/21/2006	TL
IEEE Xplore, Web	7/21/2006	TL